Briarwood Falls Condo Association Executive Board Meeting Minutes August 11, 2022 10:00 AM

(Approved September 8, 2022)

Board Members

Don Desrosiers - Pres, Pat Perna - VP, Karen Pontrelli - Treasurer/Director, Present:

Bill Cucchi, Director, Director, and John Pacheco, Director

Guests: Attendees: Chris Norman, Ron Sabatos

Zoom Participants: There were log in issues with Zoom. Only 3 people got on

before the meeting ended: Nancy Daley, Dave Musto, Carol Robbins

Board Members Absent:

Joe Geiger - Director

TOPICS	DISCUSSION				
1) Call to Order	Meeting called to order at 10:00 AM.				
2) Additions to Agenda	None				
3) Community Member Input	None				
4) Approval of Board Meeting Minutes	Minutes of July 14, 2022 Executive Board Meeting John made motion to approve the minutes Motion was seconded All approved				
5) Treasurer's Report	 Karen presented the financial statement for the last month, July 2022: Total Income: \$25,812 Total Expenses: \$19,374 Difference was \$6,438 The YTD difference income vs. expenses was a \$12,399 Total Reserves at the end of quarter: \$178,097 (Reserve reflect 2nd \$8400 withdrawal for road, driveway repairs.) Account Balances: Business Account = \$23,854 Savings Account = \$2,609 				
6) Repairs and Maintenance	 M&R Tracking Report – attached to minutes Bill summarized highlights of some recent maintenance tasks: 1 & 2 Oriole – replaced underground crushed flex pipe section blocking roof gutter drains 26 Mockingbird – replaced piece of siding to fix hole in siding 5 Grouse – replaced buckled siding Bill will try to get from siding supplier at least 2 pieces of siding color used on BF units. We have inventory of unit siding colors and will see if any unit owners have siding pieces stored in basement or garage. 				

Briarwood Falls Condo Association Executive Board Meeting Minutes August 11, 2022 10:00 AM (Approved September 8, 2022)

7) Waivers	 76 Mockingbird – installed French drain to eliminate flooding problem at entrance to porch and front door. 5 Mockingbird – repaired loose shingle and flashing on roof 2 Snowbird – had Pioneer Sealcoat repair crack in walkway 79 Mockingbird – repaired loose siding 10 Oriole - added drain extension to garage roof drain alongside of garage to eliminate water collection at kitchen door enterance. 1 Snowbird – continued to work on drain water overflow into garage. Had Affordable Door increase closing pressure of garage door but still have problem. Looking at adding flex strip barrier in front of door 3 Snowbird – filled sink hole in drive way just in front of garage with lots of cold-patch asphalt Bill had 3 waivers: 4 Mockingbird – sealcoat driveway 79 Mockingbird – replace top panel of garage door with panel with windows 3 Snowbird – resubmitted due to six-month time out to add double window in living room and window in basement
	All approved
8) Common Condo Fee	 Don requested motion for discussion. Pat made motion and Bill 2nd to open discussion on common fee proposal. Discussion addressed importance for getting the committee established and to develop a plan to get the Common Fee presentation out to all unit Owners. The initial presentation, given by Ron Sabatos at the July Community Meeting, reached only 56 people who attended that meeting at the Community Center or on Zoom. This represented 49-unit owners. Don sent out notice to recruit volunteers for the committee. Don will select five committee members from volunteer list. Pat made motion to proceed with naming the committee whose purpose will be to educate all unit owners about the common condo fee proposal. Karen 2nd motion. Pat then revised the motion to add that the first committee meeting was to be held before end of August. Karen 2nd the revised motion All approved
9) Committee	Landscape Committee – John reported no activity
Reports	 Social Activities Committee – Pat reported that plans are progressing
	Social Activities Committee – Pat reported that plans are progressing smoothly for the September 10 th picnic. A good turnout is expected.
10)Old Business	None

Briarwood Falls Condo Association Executive Board Meeting Minutes August 11, 2022 10:00 AM (Approved September 8, 2022)

11) New Business	None
12) Next board Meeting	Exec Board Meeting, September 8, 2022 at 10 AM :
13) Community Member Input	 Ron Sabatos asked regarding point of order in a meeting where if a board member wants to make a personal statement on an issue being discussed he should recuse himself/herself as a board member before making the statements. The board agreed that this was the proper procedure in accordance with Roberts Rules. Chris Norman asked that the Board issue a memo or e-mail describing the Board Officer selections made at the July 30th Special Meeting.
14) Adjourn	Don asked for motion to adjourn meeting Karen made the motion Bill 2 nd motion All approved Meeting was adjourned at 10:33 AM

Attachments: Maintenance & Repair Tracking Report July 31, 2022

Briarwood Falls Condo Association Executive Board Meeting Minutes August 11, 2022 10:00 AM (Approved September 8, 2022)

Address	11.0	Maintanance (Dec.	Date	04:4	Date	0.4
	<u>Unit</u>	Maintenance / Request	Requested	<u>Status</u>	completed	<u>Category</u>
		leak around her cellar french		I tried to fix it a month ago and		
80 Mockingbird EAGLE	doors		srtill having problem. Tim			
			Brunet looked at it and is			
			trying to find the cause of the			
			leak. Reassigned to Dave		DOOR BACK	
			Oleszewski 05/01. Dave found			
			andn repaired a			
			problestopped most of the			
			40/40/0004	leak, but still another issue.		14/11D 014/1/11/IT
27 Mockingbird	EAGLE	Leak between window panes	12/16/2021	Slocomb replacing		WINDOW UNIT
		french drain clogged		05/27/22 found the french		
1&2 oriole eagle			drain collapsed and			
		2/28/2022	cloggedgoing to dig down another 4-5 feet and see if		drain	
				Okif not going to tie into		
00		lanta in aidina	2/40/2022	another drain		a talia a
26 mockingbird	cardinal	hole in siding	3/10/2022	delay in getting siding		siding
13 snowbird	RANCH	all 3 doors need trim painted	4/3/2022	deleccio mettino elelico		PAINT
5 Grouse	EAGLE	replace damaged siding	4/44/0000	delay in getting siding		SIDING VINYL
78 Mockingbird	EAGLE	wash house	4/14/2022	D 0	0/00/0000	POWER WASH UNIT
69 Mockingbird	EAGLE	wash and seal deck	16-Apr	Dave O	6/30/2022	POWER WASH UNIT
9 Oriole	RANCH	drainage issue by kitchen stairs	4/21/2022	Estimate from Nick White		DRAINAGE
				E		
9 Oriole	RANCH	garage door steps crumbling	4/21/2022	Estimate from Nick White		WALKWAY & STEPS
9 Oriole	RANCH	sloping front stairs	4/21/2022	getting two estimates to raise		WALKWAY & STEPS
			., = ., = -	steps and also 6 Oriole		
9 Oriole	RANCH	Paint shutters side of house	4/21/2022	Paint had frozen over		PAINT
				winterpicking up new paint		
		Drainage issue in rear of homes		Joe and I are meeting Killingly		
67,69 Mockingbir	d		4/25/2022	engineering 06/09/22 to see		DRAINAGE
				what they recommend		
69 Mockingbird	EAGLE	clean out rear drains	5/1/2022			DRAINAGE
14 Oriole	RANCH	window seal failure	4/27/2022	Gave to Tim 05/12/22	6/28/2022	WINDOW UNIT
various	RANCH	Paint all phase 1 house door	5/1/2022	Dave Oleszewski submitting		PAINT
various		trims	0/1/2022	estimate.		7747
12 Snowbird RANCH	Storm door blew open and		Joe made temp repairs to get			
	damaged trim and soffitt	9-May	storm door to latch. Home		DOOR BACK	
		oa,	owner needs to repair door			
				trim and soffitt.		
6 starling	RANCH	dip/hole in walkway	5/26/2022	done by Pioneer Sealcoat	6/22/2022	WALKWAY & STEPS
8 oriole	RANCH	hole in rip rap wall	5/26/2022			LANDSCAPE
8 oriole 13 oriole	RANCH RANCH	powerwask back of house	5/30/2022			LANDSCAPE SIDING VINYL
13 oriole	RANCH	powerwask back of house deck needs repairs and	5/30/2022			SIDING VINYL
13 oriole 13 oriole	RANCH RANCH	powerwask back of house deck needs repairs and restained	5/30/2022 5/30/2022			SIDING VINYL DECK
13 oriole 13 oriole 13 oriole	RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted	5/30/2022 5/30/2022 5/30/2022		6/8/2022	SIDING VINYL DECK MISELLANIOUS
13 oriole 13 oriole 13 oriole 5 mockingbird	RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure	5/30/2022 5/30/2022 5/30/2022 6/2/2022	gave to Tim 06/03/22	7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole	RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022	not frozenfixed		SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird	RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022		7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird	RANCH RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022	not frozenfixed gave to Tim	7/1/2022 6/10/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest	RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022	not frozenfixed gave to Tim gave to Tim	7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/22/2022	not frozenfixed gave to Tim	7/1/2022 6/10/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022	not frozenfixed gave to Tim gave to Tim	7/1/2022 6/10/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/22/2022	not frozenfixed gave to Tim gave to Tim	7/1/2022 6/10/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 mockingbird 1 owl's nest 5 mockingbird 15 oriole	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/22/2022 6/19/2022	not frozenfixed gave to Tim gave to Tim	7/1/2022 6/10/2022 7/1/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole	RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH CARDINAL	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/22/2022 6/19/2022 6/19/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22	7/1/2022 6/10/2022 7/1/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird	RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH CARDINAL RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird	RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH CANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/2/2022 6/19/2022 6/19/2022 19-Jun	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim	7/1/2022 6/10/2022 7/1/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird	RANCH CARDINAL RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal sider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird	RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH CARDINAL RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 10 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird	RANCH CARDINAL RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 7/5/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY WINDOW BASEMENT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird	RANCH CARDINAL RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal sider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 19 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird	RANCH CARDINAL RANCH RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/22/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 7/5/2022 6/30/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY WINDOW BASEMENT DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole	RANCH CARDINAL RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w fill crack between garage and	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 7/5/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY WINDOW BASEMENT
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird 3 mockingbird	RANCH CARDINAL RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022 6/28/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 6/30/2022 6/30/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 19 oriole 11 mockingbird 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird	RANCH CARDINAL RANCH RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w fill crack between garage and	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/22/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest filled in around large rock with	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 7/5/2022 6/30/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird 3 mockingbird	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal sider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w fill rack between garage and d/w fill rack between garage and d/w	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022 6/28/2022 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest filled in around large rock with cold patch	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 6/30/2022 6/30/2022 6/30/2022 7/7/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird 3 mockingbird	RANCH CARDINAL RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022 6/28/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest filled in around large rock with cold patch reattached downspout elbows	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 6/30/2022 6/30/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird 4 owl's nest	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal side slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w fill in around large rock in d/w reattach downspout elbows	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022 6/28/2022 6/29/2022 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest filled in around large rock with cold patch reattached downspout elbows after paving	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 6/30/2022 6/30/2022 7/7/2022 6/29/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY DRIVEWAY DRIVEWAY
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 10 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird 13 mockingbird 14 oriole 10 snowbird 11 mockingbird 11 mockingbird 11 mockingbird 11 mockingbird 12 mockingbird 13 mockingbird 14 owl's nest 11 snowbird	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal aside slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w fill in around large rock in d/w reattach downspout elbows clean out clogged gutter	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/8/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022 6/29/2022 6/29/2022 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest filled in around large rock with cold patch reattached downspout elbows after paving cleaned out gutter	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 6/30/2022 6/30/2022 6/30/2022 7/7/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY DRIVEWAY DRIVEWAY GUTTER & DOWNSPOU
13 oriole 13 oriole 13 oriole 5 mockingbird 9 oriole 11 mockingbird 1 owl's nest 5 mockingbird 15 oriole 8 oriole 14 oriole 10 snowbird 2 mockingbird 11 mockingbird 4 owl's nest	RANCH	powerwask back of house deck needs repairs and restained front door lights rusted window seal failure rear faucet frozen window seal in 4 season room wash back of garage window seal side slider leak in garage 2 drains clogged 3 drains clogged window seal paint front door fill crack between garage and d/w remove plastic window well cover fill crack between garage and d/w fill crack between garage and d/w fill in around large rock in d/w reattach downspout elbows	5/30/2022 5/30/2022 5/30/2022 6/2/2022 6/3/2022 6/8/2022 6/8/2022 6/8/2022 6/19/2022 6/19/2022 19-Jun 6/22/2022 28-Jun 6/29/2022 6/28/2022 6/29/2022 6/29/2022	not frozenfixed gave to Tim gave to Tim gave to Dave O 06/22/22 gave to Tim filled gap with cold patch at 1 and 2 MB removed plastic cover filled gap with cold patch at 3 and 4 MB filled gap with cold patch at 3 and 4 owl's nest filled in around large rock with cold patch reattached downspout elbows after paving	7/1/2022 6/10/2022 7/1/2022 7/1/2022 7/1/2022 6/30/2022 6/30/2022 6/30/2022 7/7/2022 6/29/2022	SIDING VINYL DECK MISELLANIOUS WINDOW UNIT OUTSIDE FAUCET WINDOW UNIT POWER WASH UNIT WINDOW UNIT ROOF SHINGLES DRAINAGE DRAINAGE WINDOW UNIT PAINT DRIVEWAY DRIVEWAY DRIVEWAY DRIVEWAY